

PWIS-free

The PWIS-free requirement is applied mainly in the automotive industry. Products which exude or have attached to them substances like silicone, wax or stripping agents may not be used in production stages prior to the painting process, as contact with these substances gives rise to paintwork flaws.

Absence of PWIS is in definition as follows:

- During the production of components and assemblies PWIS may not be a content of the elements in the basic material or of the operating supplies as well as of the raw material.
- Liquid or paste-like raw materials like grease that do not impair surface wetting in the coating process.
- Items that consist of PWIS-free parts and that contain PWIS-free greases.

We hereby confirm that our conduit series **PARAB** does not contain any Paint-Wetting Impairment Substances acc. to our best knowledge.

Furthermore, we obtained the confirmation by our supplier that the delivered Polyamide 12 (PA12) resin is free of PWIS in advance.

REIKU GmbH

Kabelschutzsysteme
Robert-Besch Strees

51674-Wehrt-Bonnig

www.reiku.de

REIKU GmbH